

DESCRIPTION	DATE
Fuses	May 24, 2017

Identification: **CV 087, Section A-70**

The anomaly reported November 21, 2016 on this equipment and section has been repaired and eliminated (heating fuse clips).

No further action is required.

Priority: **CV 087, Section A-70**

<b>RECOMMENDATION:</b>		1	2	3	4	5		
	No Action	Low					High	Don't Run